

Examples of how to hook up 3 ϕ or 1 ϕ Current Transformers (CTs) taken from the Revenue Metering Standard




Figure 4: Three Phase CT Layout